

CABLE CLEATS FOR SINGLE CABLES

PART NUMBER CROSS REFERENCE

ABB T&B

Made in Korea

TALON[®] CABLE CLEATS



Made in USA

ABBCCBSRT (mounting bracket)	Substitute R15 for R00 in Talon Cable Cleat Part Number
ASCC 2832	T1-04 - F1H4R00 - 000 ^{NOTE}
ASCC 3034	T1-04 - F1H4R00 - 000
ASCC 3236 / ASCC 3438	T1-04 - F1H4R00 - 000
ASCC 3640 / ASCC 3842	T1-04 - F1H4R00 - 000
ASCC 4044 / ASCC 4246	T1-04 - F1H4R00 - 000
ASCC 4448 / ASCC 4650	T1-04 - F1H4R00 - 000
ASCC 4852	T1-04 - F1H4R00 - 000 / T1-05 - F1H4R00 - 000 ^{NOTE}
ASCC 5054	T1-04 - F1H4R00 - 000 / T1-05 - F1H4R00 - 000 ^{NOTE}
ASCC 5256 / ASCC 5458	T1-05 - F1H4R00 - 000
ASCC 5660 / ASCC 5862	T1-05 - F1H4R00 - 000
ASCC 6064 / ASCC 6266	T1-05 - F1H4R00 - 000
ASCC 6468 / ASCC 6670	T1-05 - F1H4R00 - 000
ASCC 6872 / ASCC 7074	T1-05 - F1H4R00 - 000
ASCC 7276 / ASCC 7478	T1-05 - F1H4R00 - 000
ASCC 7680	T1-05 - F1H4R00 - 000 / T1-06 - F1H4R00 - 000 ^{NOTE}
ASCC 7682	T1-05 - F1H4R00 - 000 / T1-06 - F1H4R00 - 000 ^{NOTE}
ASCC 8084 / ASCC 8286	T1-06 - F1H4R00 - 000
ASCC 8488 / ASCC 8690	T1-06 - F1H4R00 - 000
ASCC 8892	T1-06 - F1H4R00 - 000
ASCC 9094	T1-06 - F1H4R00 - 000
ASCC 9296 / ASCC 94106	T1-06 - F1H4R00 - 000

NOTE: To select the proper cable cleat (and cable cleat liner, when required), physical cable dimensions must be confirmed. Refer to the appropriate Talon[®] Cable Cleat Data Sheet to determine the part number for the respective cable size. Other cable cleat frame sizes are available on request.



HOLD THE CABLES. HUG THE RUNG.[®]

Talon Products, LLC
 Web: HugTheRung.com
 Phone: +1 985 956 7600

Trust **TALON[®]** cable cleats to maintain constant vigilance over your cables and support system.