

CABLE CLEATS FOR TREFOIL CABLES

PART NUMBER CROSS REFERENCE

Panduit
CCSSTR, CCPLTR

TALON® CABLE CLEATS



Made in USA

CBH15L50-V6 (mounting bracket)	Substitute R40 for R00 in Talon Cable Cleat Part Number
CBH20L50-V6 (mounting bracket)	Substitute R30 or R40 for R00 in Talon Cable Cleat Part Number ^{NOTE}
CBH25L50-V6 (mounting bracket)	Substitute R20 or R30 for R00 in Talon Cable Cleat Part Number ^{NOTE}
CBH30L50-V6 (mounting bracket)	Substitute R10 or R15 for R00 in Talon Cable Cleat Part Number ^{NOTE}
CCSS TR 2025 -X	T1-04 - F1H4R00 - 000 / T1-05 - F1H4R00 - 000 ^{NOTE}
CCSS TR 2328 -X	T1-05 - F1H4R00 - 000 / T3-03 - F1H4R00 - 000 ^{NOTE}
CCSS TR 2632 -X	T3-03 - F1H4R00 - 000 ^{NOTE}
CCSS TR 3036 -X	T3-03 - F1H4R00 - 000
CCSS TR 3440 -X	T3-03 - F1H4R00 - 000 / T3-04 - F1H4R00 - 000 ^{NOTE}
CCSS TR 3844 -X	T3-04 - F1H4R00 - 000
CCSS TR 4248 -X	T3-04 - F1H4R00 - 000 / T3-05 - F1H4R00 - 000 ^{NOTE}
CCSS TR 4652 -X	T3-05 - F1H4R00 - 000
CCSS TR 5057 -X	T3-05 - F1H4R00 - 000
CCSS TR 5461 -X	T3-05 - F1H4R00 - 000 / T3-06 - F1H4R00 - 000 ^{NOTE}
CCSS TR 5865 -X	T3-06 - F1H4R00 - 000
CCSS TR 6269 -X	T3-06 - F1H4R00 - 000
CCPL TR 2228 -X	T1-04 - F1H4R00 - 000 / T1-05 - F1H4R00 - 000 / T3-03 - F1H4R00 - 000 ^{NOTE}
CCPL TR 2633 -X	T3-03 - F1H4R00 - 000 ^{NOTE}
CCPL TR 3139 -X	T3-03 - F1H4R00 - 000
CCPL TR 3745 -X	T3-04 - F1H4R00 - 000
CCPL TR 4352 -X	T3-04 - F1H4R00 - 000 / T3-05 - F1H4R00 - 000 ^{NOTE}
CCPL TR 5060 -X	T3-05 - F1H4R00 - 000 / T3-06 - F1H4R00 - 000 ^{NOTE}

NOTE: To select the proper cable cleat (and cable cleat liner, when required), physical cable dimensions must be confirmed. Refer to the appropriate Talon® Cable Cleat Data Sheet to determine the part number for the respective cable size. Other cable cleat frame sizes are available on request.



HOLD THE CABLES. HUG THE RUNG.®

Talon Products, LLC
Web: HugTheRung.com
Phone: +1 985 956 7600

Trust **TALON**® cable cleats to maintain constant vigilance over your cables and support system.